

Figure 1 (supplement to FER-172). Location of Newport-Inglewood fault zone recommended for zoning across SW Newport Mesa. Trenches excavated by Earth Technology (only selected trenches shown).

172-13