

Figure 13 (FER-245)

Faults recommended for inclusion in new Alquist-Priolo Earthquake Fault Zones (EFZ) on the Point Loma 7.5' quadrangle. Refer to text for sources of fault traces and justification for zoning.

Faults to be zoned indicated by heavy red line.