
Plate 1 (FER-246) - Recommended zoning on the Hector 7.5-minute quadrangle
Current Alquist-Priolo Earthquake Fault Zones, including faults zoned
Generalized trace of faults proposed for new Alquist-Priolo EFZ
0rl; 2v(w)
1999 surface fault rupture and trace fractures from field mapping
slip measurements in centimeters; rl= right lateral, ll= left lateral, v(w)= vertical component (letter in parentheses indicates which side is down - w-west or e-east)
other fractures (1999) from field mapping
aerial photo lineament from 1952-53 imagery
1a
locality discussed in text
N
0 rl; 2 v (w)
0 rl; 0 v
0 rl; 0 v
0 rl; 0 v
3.5 ll; 0 v
Fault "B" (Hart, 1987a)
Pisgah fault
Hector Mine
PIPELINE
TRANSMISSION
SUB STA
STEEL TOWER TRANSMISSION LINE
LAVA
ROAD LEGEND
Improved Road
Unimproved Road
CALIF.