Plate 2 FER 27

The Country Club fault (~~Ventura~~ Saticoy quadrangle).

Color code:

Green = Weber, et al. (1975)

Yellow = Sarna-Wojcicki, et al. (1976)

Red = Mukae and Turner (1975) water barriers

fault, dashed where approximate, dotted where concealed, queried where inferred

lineament

scarp

well locations and cross-section location from Turner, 1975

(all uncolored data from Smith, this report)



Weber, et al: DWR shows ground water barrier (in this general area) along "Saticoy fault", so does Turner, 1975 - at least has had Late Quaternary movement.

Note: in both cases the rows do not // the lineations; further, more recent photos show that newly planted trees grow "differentially" in the same relationships: TCS