

FER 28
Plate 3. The Red Mountain fault in Pitas Point quadrangle.

GENERAL RECOMMENDATIONS:

Zone those traces noted, perhaps zone traces shown by Weber, et al. (1975) west of Madranio Canyon. Add note on east end of zone to the effect that the Red Mountain fault zone extend's east of the zone, however it is not known to be active, nor is it known where the active trace is if there is one.

scarps (fault and landslide)

— · — · — air photo lineament with description

Qt = terrace deposits (yellow)

fan = ~~stream~~ alluvial fan (yellow stripe)

/ = landslide (colored red)

fault traces (slightly modified) from Weber, et al. (1975) (purple) and Dibblee (1947) (pink).

28-1