Figure 3A
FER-70

modified from Barrows, et al, 1976, Geology and fault activity of the Palmdale segment of the San Andreas fault zone, Los Angeles County, CA:

CDMG OFR 76-6 LA
PALMDALE W/W2

Faults to be zoned for revised SSZ Maps (Based on CDMG OFR 76-6 LA; ~~and~~ preliminary faultmap of Palmdale segment, San Andreas fault, by Kahle, Smith & Beeby; and personal communications with Kahle, Barrows, Beeby, and Smith on Jan 23, 1978)

Recommended new zone boundary (approximate; adjust to features of base map); show orange-colored faults on revised maps.

Segments of Quat flts where flt does not appear to cut Pleist. unit



70-5