Fig. 4a (FER-85). Locations of fault traces based on interpretation of aerial photos (Fairchild, 1939) & field checking, Nov. 1978. Additional field data & notes of Feb. 1979 are in red.

Scarps; hachures on down side; dashed lined indicates poorly defined or modified.

Zonal lineaments or contrasts in vegetation & soil; dashed where vague.

Fig 4a (FER-85)

STATE OF CALIFORNIA
DEPARTMENT OF WATER RESOURCES

HEMET QUADRANGLE
CALIFORNIA—RIVERSIDE CO.
7.5 MINUTE SERIES (TOPOGRAPHIC)
NW/4 HEMET 15' QUADRANGLE



Fairchild
Photo interp based on 1939 photos C5750 series, flights 210 & 232, Whittier collection
EMH - Oct 1978

85-3