

Figure 3c (to FER 96). Plot of recently active fault traces of Sargent fault zone, showing fault-related geomorphic features based on air photo interpretation and limited field checking. (See list of references for aerial photos used).