

FER-101

Figure 7. Locations where fault creep has been verified, and recommended SSZ revisions.

⊙ dot marks location of point data (±50 ft)

line marks location of a series of data points less than 50 ft apart

For site descriptions see Table X2.

× = site of landslide damage

101-3