

Figure 12. Annotated fault map of the Vallecitos area, showing faults as mapped by the writer during this investigation. Map area includes the northern third of the La Costa Valley quadrangle and the southern third of the Livermore quadrangle, Alameda County, California.

FER-104

104-2