GILROY QUADRANGLE
CALIFORNIA—SANTA CLARA CO.
7.5 MINUTE SERIES (TOPOGRAPHIC)
SE/4 MORGAN HILL 15' QUADRANGLE



FER-121. Figure 6A. Results of Air Photo Interpretation, with selected field data.

LT = linear trough
LD = linear drainage
DD = deflected drainage
t = tonal
BIS = break in slope
B = bench
SP = sag pond
CD = closed depression
= scarp
SHT = side-hill trench
SHB = side-hill bench
S = saddle



FER-121. Figure 6B. Air photo interpretation results, with selected field data.

t = tonal
CD = closed depression
S = saddle
LD = linear drainage
BIS = break in slope
b = bench
SHT = side-hill trench
BTD = be-toed drainage
DD = deflected drainage

121-3