

Fault traces of Dibblee (1973a)

Fault traces of Radbruch-Hall (1974)

Fault traces of Bryant (this report)

Figure 4a (to FER-122). Plot of recently active fault traces recommended for zoning for special studies. Annotations show geomorphic features indicating Holocene activity based on air photo interpretation by Bryant.