

Faults mapped by Helley and Herd (1977). Solid line where well-located, dashed where approximately located, querried where uncertain, dotted where concealed.

Landslide deposit larger than 500 feet in longest dimension, from Sims & Frizzell (1976).

Landslide deposit smaller than 500 feet in longest dimension, from Sims & Frizzell (1976).

Alluvial deposits, including stream, floodplain, fan, and some terrace deposits. From Sims & Frizzell (1976).

Colluvial deposits. From Sims & Frizzell (1976).

Bedding attitude. From Sims, et al (1973).

Locality number referred to in text.

Figure 2 (to FER-128). Recently active faults of the "Lake Berryessa fault" zone in the Lake Berryessa quadrangle mapped by Helley and Herd (1977). Fault traces plotted from 1:125,000 map using Zoom Transfer Scope. Annotations by Bryant (this report).