

MAP EXPLANATION

bench

Faults mapped by Helley and Herd (1977). Solid line where well-located, dashed where approximately located, queried where uncertain, dotted where concealed. Annotations by Bryant (this report).

50

Bedding attitude. From Fox, et al (1973).

Figure 2 (to FER-131). Recently active faults of the "Milliken Peak fault" zone in the Sonoma quadrangle mapped by Helley and Herd(1977). Fault traces plotted from 1:125,000-scale map using Zoom Transfer Scope.

(SEARS POINT) 1560 III NW

(CUTTINGS WHARF) 1560 III NE

SCALE 1:24 000

0 — 1 MILE

2000 3000 4000 5000 6000 7000 FEET

0 — 1 KILOMETER

ROAD CLASSIFICATION

Heavy-duty — Light-duty

Medium-duty — Unimproved dirt

State Route

CONTOUR INTERVAL 20 FEET
LINES REPRESENT 5 FOOT CONTOURS
DATUM IS MEAN SEA LEVEL

WITH NATIONAL MAP ACCURACY STANDARDS
EY, DENVER, COLORADO 80225, OR WASHINGTON, D. C. 20242
APHIC MAPS AND SYMBOLS IS AVAILABLE ON REQUEST

CALIF

QUADRANGLE LOCATION

SONOMA, CALIF.

SW/4 SONOMA 15' QUADRANGLE

N3815—W12222.5/7.5

1951

PHOTOREVISED 1968

AMS 1560 IV SW—SERIES V895

131-2