STATE OF CALIFORNIA
GOODWIN J. KNIGHT, GOVERNOR
FRANK B. DURKEE, DIRECTOR OF PUBLIC WORKS
HARVEY O. BANKS, STATE ENGINEER

GEYSERVILLE QUADRANGLE
CALIFORNIA—SONOMA CO.
7.5 MINUTE SERIES (TOPOGRAPHIC)
NW/4 HEALDSBURG 15' QUADRANGLE

MAP EXPLANATION

Faults considered to have been active during Holocene time; solid line where accurately located, long dash where approximately located, short dash where inferred, dotted where concealed; query indicates additional uncertainty.

SOURCE OF FAULT TRACES

- Bryant (this report)
- Herd, et al. (1977)
- Herd (in press)
- Huffman & Armstrong (1980)
- McLaughlin (1978)

135-2



Figure 5d (to FER-135). Faults in the Geyserville quadrangle recommended for zoning for special studies. See map explanation for sources of fault traces.