

FER-143. Figure 4B. Fault-related features in the North of Oildale quadrangle visible on aerial photographs. Solid lines indicate location of well-defined features. Dashed lines indicate features that are broad or less well defined.

t = tonal lineaments
s = saddle
cld = curvilinear drainages (or aligned curvilinear drainages)
ld = linear drainage
= scarp, hatchures on down side

143-7