FER-150. Figure 56. Fault-related features and diagnostic geomorphic surfaces in the Pentland quadrangle visible on U.S. Department of Agriculture (1952) aerial photographs. Solid line indicates feature or contact appears well-defined; dashed line indicates features or contacts are less well-defined.

= scarp or escarpment which appears to coincide with a contact between two different rock units; may be fault-produced or result solely from folding

= contact, well-defined and accurately located

= contact, poorly defined or approximately located

t = tonal lineation

Qa = alluvium (probably Holocene)

Qoa = older alluvium (probably Pleistocene)

= landslide deposits (selectively shown)



on 1953

16°
TRUE NORTH
MAGNETIC NORTH
APPROXIMATE MEAN DECLINATION, 1953

SCALE 1:24000

1 ½ 0 1 MILE

1000 0 1000 2000 3000 4000 5000 6000 7000 FEET

1 .5 0 1 KILOMETER

CONTOUR INTERVAL 25 FEET
DATUM IS MEAN SEA LEVEL

RECEIVED
1957
MAP FILE

CALIF
QUADRANGLE LOCATION

ROAD CLASSIFICATION

Heavy-duty
Medium-duty
Light-duty
Unimproved dirt
U. S. Route
State Route

PENTLAND, CALIF.
N3500—W11915/7.5
1953

FOR SALE BY U. S. GEOLOGICAL SURVEY, DENVER 2, COLORADO OR WASHINGTON 25, D. C.
A FOLDER DESCRIBING TOPOGRAPHIC MAPS AND SYMBOLS IS AVAILABLE ON REQUEST

150-9