FER-151, Figure 2. Location of fault of Turner (1897; orange highlighting), of inferred faults of Ford and Swanson (dotted), and of lineaments identified on U.S. Department of Agriculture (1972) aerial photographs (not highlighted). Durrell (1972; 1976) does not show any faults cutting Quaternary deposits in this area.