

Figure 3 (to FER-153). Recently active segments of the northern Owens Valley, Fish Slough, and White Mountains frontal fault zones in the Bishop and White Mountain Peak quadrangles. Mapping is by Bryant (this report), based on air photo interpretation and field inspection.

153-4