

MAP EXPLANATION

Faults considered to have been active during Holocene time; solid line where accurately located, long dash where approximately located, short dash where inferred, dotted where concealed; query indicates additional uncertainty.

Source of fault traces

- Bateman (1965)
- Bryant (this report)

Figure 5d (to FER-158). Faults in the Mt. Tom 7.5' quadrangle recommended for zoning for special studies.

SCALE 1:24 000

CONTOUR INTERVAL 40 FEET
NATIONAL GEODETIC VERTICAL DATUM OF 1929

THIS MAP COMPLIES WITH NATIONAL MAP ACCURACY STANDARDS
FOR SALE BY U. S. GEOLOGICAL SURVEY, DENVER, COLORADO 80225, OR RESTON, VIRGINIA 22092
A FOLDER DESCRIBING TOPOGRAPHIC MAPS AND SYMBOLS IS AVAILABLE ON REQUEST

QUADRANGLE LOCATION

ROAD CLASSIFICATION

Light-duty road, all weather, improved surface

Unimproved road, fair or dry weather

MOUNT TOM, CALIF.
SW/4 MT. TOM 15' QUADRANGLE
N3715—W11837.5/7.5

1982 158-1

DMA 2258 I SW—SERIES V895

Mt. Tom SW, Ca
Sierra Proj.
J. Schwabe