

Figure 2A. Ortigalita fault traces of other workers, with summary of evidence for most recent unit offset.

MAP EXPLANATION

Fault: Solid line indicates accurately located; dashed line, approximately located; dotted where concealed; queries indicate additional uncertainty.

T-8 Trench of U.S.B.R. (approximate location) with trench number assigned by Anderson, LaForge, & Andres (1982).

Shutter ridge Comments on fault maps of Anderson, LaForge, & Andres (1982).

Concealed by landslide Comments by Manson (this report)

Evidence of recency of faulting:

① Age of oldest unit not faulted.

② Age of youngest unit faulted.

1 Holocene

2 Pleistocene

3 Cretaceous or Jurassic.

Age dates from Dibblee (1975).

Sources of fault traces:

- Anderson, LaForge, & Andres (1982)
- Cotton (1972)
- Dibblee (1975)
- Letts (1982)
- Anderson (unpublished)