

Figure 3 (to FER-167). Log of road-cut exposure of Tularcitos fault. Refer to figure 2c for location of exposure.

167-7