
FIGURE 4, SUPPLEMENT #1 to FER-174.
Map showing faults evaluated, and selected observations in the
FILLMORE QUADRANGLE
EXPLANATION
Fault, solid line where accurately located, long dash where approximately located, short dash where inferred, dotted where concealed. Bar and ball on downthrown side of scarp. Query (?) indicates additional uncertainty.
See Figure 11, FER-174 for continuation of San Cayetano Fault.
Source of information; color adjacent to trace.
orange or TKR — Rockwell, 1983.
blue or FHW — Weber and others, 1975.
green or IC — Cemen, 1977
no color or JEK — This report.
Bedrock Landslide, FHW
Possible Bedrock Landslide? FHW
Closed Depressions
North Fillmore
Fillmore
Brownstone Reservoir
Kenney Grove
Sespe
Water Tank
Reservoir
Oat Mtn
San Cayetano Mtn
SCALE 1:24000
1 MILE
7000 FEET
1 KILOMETER
174-10
118°52'30"
34°25'