

Figure 6. 1992-1994 Recently-active traces of the Helendale fault and traces recommended for zoning. Fault traces in black are based on data and others (1992). Fault traces in green are from previous (this report). All traces are recommended for zoning, unless otherwise indicated.

MAP EXPLANATION

Recently-active fault: Solid line where accurately located, long dash where approximately located, short dash where inferred, dotted where concealed; query indicates additional uncertainty.