Figure 7B to FER-177: Recently-active traces of the Lenwood and Old Woman Springs faults, and traces recommended for zoning. Traces in black are from Morton and others (1980), locally modified where necessary. Traces in green are from Meason (Figures 4 & 5, this report). All traces are recommended for zoning, unless otherwise noted.

Fault: Solid line where accurately located; long dash where approximately located; short dash where inferred; dotted where concealed; query indicates additional uncertainty.

177-4