

Figure 3c. (FER-179) Map showing recently active fault traces interpreted from aerial photographs, field observations, and trench logs.

179-5