

Figure 4B to FER-180: Traces of the Homestead Valley, Johnson Valley, and related faults in the Melville Lake and Bighorn Canyon quadrangles. Traces and comments in black are from Morton and others (1980, sheet 7). Selected traces in orange are from Dibblee (1967c). Traces in green, and comments bordered in green, are from air photo interpretations and field observations by Manson (this report).

MAP EXPLANATION

Fault: Solid where accurately located, dashed where approximately located, dotted where concealed, query indicates additional uncertainty, hachures indicate direction scarp faces.

(f)6/5/86 Field observation, with date.

Geomorphic features indicative of fault location and/or recency:

t	tonal	shb	sidehill bench
bis	break-in-slope	ld	linear drainage
dd	deflected drainage (right-lateral sense)	s	saddle or notch
ls	landslide (mapping incomplete)		

180-6