UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

MELVILLE LAKE QUADRANGLE
CALIFORNIA—SAN BERNARDINO CO.
7.5 MINUTE SERIES (TOPOGRAPHIC)
NE/4 OLD WOMAN SPRINGS 15' QUADRANGLE

Figure 6B to FER-180: Traces of recently-active faults in the Melville Lake and Bighorn Canyon 7.5' quadrangles, and traces recommended for zoning. Traces in black are from Morton and others (1980, sheet 7). Traces in green are from Manson (this report). All traces are recommended for zoning unless otherwise indicated.

Recently-active fault: solid line indicates accurately located; long dash, approximately located; short dash where inferred; dotted where concealed; query indicates additional uncertainty.



BIGHORN CANYON, CALIF.
SE/4 OLD WOMAN SPRINGS 15' QUADRANGLE
N3415—W11630/7.5
1972

180-3