

Figure 2 (Supplement No. 2 to FER-181). Compilation of traces of the East Airfield fault and the Mesquite Lake fault. Faults shown in red and annotations are from Bryant (this report), based on air photo interpretation.