

Figure 5 (to FER-188). Recently active faults in the Hector 7.5' quadrangle based on the interpretation of aerial photographs and limited field observations by Hart (this report). Faults recommended for zoning are highlighted in yellow.