UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

STATE OF CALIFORNIA
DEPARTMENT OF WATER RESOURCES

SOLDIER PASS QUADRANGLE
CALIFORNIA–NEVADA
15 MINUTE SERIES (TOPOGRAPHIC)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

STATE OF CALIFORNIA
DEPARTMENT OF WATER RESOURCES

MAGRUDER MTN. QUADRANGLE
NEVADA–CALIFORNIA
15 MINUTE SERIES (TOPOGRAPHIC)



Figure 2b (to FER-193). Faults in the Fish Lake Valley-Northern Death Valley study area, based on available mapping by others. Boxed annotations are from air photo interpretation by Bryant (this report). Faults recommended for zoning are highlighted in yellow.

Fig 2b
193-6