

FER 195, Figure 5

Rancho California Ground Cracks

Ground cracks formed in 1987 in Temecula Valley modified from Riverside County (1988). Annotations added based on field checks in 1988 with date of observation.

left stepping cracks in asphalt f/c 1/22/88

Geomorphology suggestive of Holocene faulting shown in green.

Trace of geomorphic feature; solid line where well located, dashed where approximate. Scarp shown by tick marks on down-dropped side. t indicates tonal lineament.

Trench 1

Approximate location of trench by Schaefer Dixon Associates, field checked February 22,1988

195-3