


FER 195, Supplement 1, Figure 1.

Geomorphic and tonal features along and near the Murrieta Creek fault and locations of trenches by consulting geologists. Some features are approximately located.

EXPLANATION

- (9) locality referred to in text
- scarp
- t, 1953 tonal lineament, with date of aerial photo it was observed on.
- art. artificial (man made) lineament
- trench location
  - H - Holocene fault found
  - L - late Pleistocene fault found
  - NF- no fault found

N

0 scale 1:12,000 .5 mile

0 .5 kilometer