

FER 197, Figure 2a

Recently active faults and ground cracks on the Cinco quadrangle. Existing (1976) Special Studies zones boundaries shown in green.

All features mapped by Pampeyan and others (1988) are recommended for zoning. Previously zoned faults of Clark (1973) coincide with faults mapped by Pampeyan and others.

SCALE 1:24 000

1 ½ 0 1 MILE

1000 0 1000 2000 3000 4000 5000 6000 7000 FEET

1 .5 0 1 KILOMETRE

CONTOUR INTERVAL 40 FEET
NATIONAL GEODETIC VERTICAL DATUM OF 1929

THIS MAP COMPLIES WITH NATIONAL MAP ACCURACY STANDARDS
FOR SALE BY U. S. GEOLOGICAL SURVEY, DENVER, COLORADO 80225, OR RESTON, VIRGINIA 22092
A FOLDER DESCRIBING TOPOGRAPHIC MAPS AND SYMBOLS IS AVAILABLE ON REQUEST

CALIF
QUADRANGLE LOCATION

ROAD CLASSIFICATION

Primary highway, hard surface
Light-duty road, hard or improved surface
Secondary highway, hard surface
Unimproved road
Interstate Route
U. S. Route
State Route

INTERIOR—GEOLOGICAL SURVEY, RESTON, VIRGINIA—1976

CINCO, CALIF.

SE/4 CROSS MTN. 15′ QUADRANGLE
N3515—W11800/7.5

1972

AMS 2354 I SE—SERIES V895

197-2