

Figure 2d (to FER-206). Panamint Valley fault zone in the Panamint Valley study area, based on available mapping of others. Annotations outlined in green are from Clark (1973). Refer to Figure 3 map explanation for description of geomorphic symbols. Faults highlighted in yellow are recommended for zoning for special studies.