FER-209, Figure 2c
Recently active faults on the Fall River Mills quadrangle. Faults recommended for zoning are highlighted in yellow.



EXPLANATION

Recently active faults mapped by Wills (this report) based on interpretation of aerial photographs and limited field checking. Solid line indicates well-defined feature, dashed where approximately located, short dashed where inferred, dotted where concealed. Hachures on down-dropped side. f/c indicates locality field checked.

(7) Locality referred to in text.

Geomorphic features indicative of fault recency and/or location.

cd	closed depression	fs	faceted spur
ld	linear drainage	lr	linear ridge
shb	side-hill bench	s	saddle
t	tonal lineament	v	vegetation lineament
vod	vertically offset drainage		

Faults mapped by Peterson and Martin (1980) dashed where approximately located, dotted where concealed.

Faults mapped by Champion and Donnelly-Nolan (unpublished) dashed where approximately located, dotted where concealed.

Faults of the "Fall River fault zone" mapped by Woodward-Clyde Consultants (1987) dashed where approximately located, dotted where concealed.

Key to age of faulted and unfaulted units.

□	unit offset	Q -	Quaternary unit
○	unit not offset	L -	Late Pleistocene unit
		H -	Holocene unit

209-6