

Figure 2a (to FER-217). Recently active faults in the Surprise Valley study area, based on mapping by Hedel (1984) and air photo interpretation and limited field mapping by Bryant (this report). Faults highlighted in yellow are recommended for zoning for special studies.

217-2