Figure 2
(FER-219)



Figure 2 (FER-219) - The Oak Ridge fault zone on the Moorpark quadrangle and parts of the Santa Paula and Fillmore quadrangles. Yellow highlighting indicates faults recommended for Special Studies Zone.

geomorphic features identified in this study which may be indicative of recent faulting, hachured lines mark scarps, solid line where feature is well-defined, dashed line where feature is not as sharp, (b/s-break in slope; shb-sidehill bench; t-tonal lineament; v-vegetation lineament)

faults from Yeats (1988), excluding Bardsdale Cemetery scarp which has been re-plotted for this study

additional faults from Weber and others (1975)

selected landslides along fault zone which may be significant to interpreting recency of movement; blue shaded slide is clearly offset, lavender shaded slides are possibly offset, green shaded slides appear unaffected

219-3