

Figure 2b (FER-227) - Location of the Raymond fault zone on the El Monte and part of the Los Angeles 7.5-minute quadrangles. Sources of data indicated on map. Faults recommended for Special Studies Zone are highlighted in yellow. Solid line indicates fault is accurately located, short-dashed line indicates inferred fault, hachures point down scarp.

227-3