CALIFORNIA DIVISION OF MINES AND GEOLOGY
JAMES E. SLOSSON, STATE GEOLOGIST

STATE OF CALIFORNIA
THE RESOURCES AGENCY
DEPARTMENT OF CONSERVATION

source unknown

DEVORE QUADRANGLE
CALIFORNIA—SAN BERNARDINO CO.
7.5 MINUTE SERIES (TOPOGRAPHIC)
NW/4 SAN BERNARDINO 15' QUADRANGLE



NOTICE

Effective January 1, 1994, the name "Special Studies Zones" has been changed to **"Earthquake Fault Zones"** and Chap. 7.5, Div. 2, of the Public Resources Code has been renamed the **"Alquist-Priolo Earthquake Fault Zoning Act."**

MAP EXPLANATION

Potentially Active Faults

Faults considered to have been active during Quaternary time; solid line where accurately located, long dash where approximately located, short dash where inferred, dotted where concealed; query (?) indicates additional uncertainty. Evidence of historic offset indicated by year of earthquake-associated event or C for displacement caused by creep or possible creep.

Special Studies Zone Boundaries

These are delineated as straight-line segments that connect consecutively numbered turning points so as to define one or more special studies zone segments.

REFERENCES USED TO COMPILE FAULT DATA

Devore Quadrangle

Blue — Dutcher, L.C., and A.A. Garrett, 1963, Geologic and hydrologic features of the San Bernardino area, California; with special reference to underflow across the San Jacinto fault: U.S. Geological Survey Water-Supply Paper 1419, 114, p.

Yellow — Hope, R.A., 1969, Map showing recently active breaks along the San Andreas and related faults between Cajon Pass and Salton Sea, California: U.S. Geological Survey open-file map.

Green — Morton, D.M., unpublished mapping of the Devore quadrangle (1973, personal communication).

Red — Sharp, R.V., 1972, Map showing recently active breaks along the San Jacinto fault zone between the San Bernardino area and Borrego Valley, California: U.S. Geological Survey Miscellaneous Geologic Investigations Map I-675.

Map 1a (FER-240). Earthquake Fault (Special Studies) Zones of the Devore quadrangle and references used to compile the faults (CDMG, 1974). NV indicates selected faults not verified as recently active based on air photointerpretations. Other faults are evaluated on Map 2a. NF indicates trench locations where no active fault was found.

240-1