

Figure 3. (FER-242) Fractures in natural terrain resulting from the 17 January 1994 Northridge earthquake. See Figure 1 for location.

241-4