

FER 195, Figure 6a

Zones of ground cracking and fault related geomorphology on the Pechanga quadrangle. These faults are sufficiently active and well defined for zoning under the Alquist-Priolo Special Studies Zones Act.

SCALE 1:24 000

1 ½ 0 1 MILE

1000 0 1000 2000 3000 4000 5000 6000 7000 FEET

1 .5 0 1 KILOMETER

CONTOUR INTERVAL 20 FEET
NATIONAL GEODETIC VERTICAL DATUM OF 1929

GN MN 0°06' 2 MILS 14½° 258 MILS

UTM GRID AND 1975 MAGNETIC NORTH DECLINATION AT CENTER OF SHEET

195-4