FAULT EVALUATION REPORT 54
PLATE 1. The Oak Ridge fault, eastern end.
Fault, dashed where approximate, dotted where concealed.
Source of data
Weber, et al. (1975), after various authors
Bain (1954)
Jestes (1958)
Santa Clara Valley fault of Jestes (1958)
Weber, et al (1975): Modified fault scarp
Weber, et al (1975): Faceted spur
Weber, et al (1975): Shutter ridge ?
buried under Qal
under Qal
under Qls
OAK RIDGE
SANTA CLARA
SAN FRANCISCO
SESPE
RIVER
Fillmore
ROAD CLASSIFICATION
Heavy-duty
Medium-duty
Light-duty
Unimproved dirt
State Route
QUADRANGLE LOCATION
CALIF
Mapped, edited, and published by the Geological Survey
Control by USGS and USC&GS
Topography from aerial photographs by multiplex methods and by plane-table surveys 1952. Aerial photographs taken 1947
Polyconic projection. 1927 North American datum
10,000-foot grid based on California coordinate system, zone 5
Dashed land lines indicate approximate locations
1000-meter Universal Transverse Mercator grid ticks, zone 11, shown in blue
Revisions shown in purple compiled in cooperation with California Department of Water Resources from aerial photographs taken 1969. This information not field checked
FILLMORE, CALIF.
NW/4 PIRU 15' QUADRANGLE
N3422.5—W11852.5/7.5
1951
PHOTOREVISED 1969
AMS 2252 IV NW—SERIES V895
54-1
UTM GRID AND 1969 MAGNETIC NORTH DECLINATION AT CENTER OF SHEET
CONTOUR INTERVAL
FOR SALE BY U. S. GEOLOGICAL SURVEY, DENVER, CO
VAL VERDE, CALIF.
NW/4 SANTA SUSANA 15' QUADRANGLE
N3422.5—W11837.5/7.5
1952
PHOTOREVISED 1969
AMS 2252 I NW—SERIES V895