

Figure 6a (to FER-132). Faults in the Clearlake Highlands quadrangle recommended for zoning for special studies. See map explanation for sources of fault traces.