MAP EXPLANATION

Fault or lineament of Knuepfer (1977) - Solid line indicates well-defined photogeologic lineament or well-defined surficial evidence of faulting; dashed line poorly-defined photogeologic lineament or ambiguous surficial evidence of faulting; (nature of lineament uncertain); dotted line is inferred extension of fault where concealed by recent sediments.

scarp — Annotations by Knuepfer (1977)

saddle — Annotations by Bryant (this report). Underline in green, rather than box, indicates response or modification to observations of Knuepfer (1977).

30 — Attitude of bedding from Sims, et al (1973).

136-4

Figure 4a (to FER-136). Cannon Hills segment (northern section) of the Vaca-Montezuma Hills fault zone.