

FER-145. Figure 3D. Air photo and field data, Edison quadrangle.

= scarp (hachures on downhill side)

= tonal lineament

= location of trench

= landslide

= fan

NV = No features indicative of recent faulting visible on aerial photographs

Data in black from aerial photographs.

Data in red from field observations.

Yellow highlight indicates those features which were probably produced by recent fault movement.