


Figure 3 (Supplement No. 2 to FER-181). Faults in the Yucca Valley North and Yucca Valley South quadrangles, based on mapping by Grimes (1987). Annotations are by Bryant (this report).

181-16